Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: LIBERTY SECTION 14 NWNE CENTRAL FACILITY

Field Name: PARSHALL Well File #:

Date Incident: 3/7/2016 Time Incident: 21:30 Facility ID Number: 231429-01
County: MOUNTRAIL Twp: 151 Rng: 91 Sec: 14 Qtr: NW NE

Location Description:

Submitted By: Danielle Dupay Received By:

Contact Person: Danielle Dupay

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 32 Barrels 32 Barrels 32 barrels

Description of Other Released Contaminant:

Manufactured Salt Water/Heavy Water

Inspected: Written Report Received: 3/16/2016 Clean Up Concluded: 3/8/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The standing liquids on ground were removed with vac truck immediately, the man way on the tank was closed and the contaminated soils have been removed and are being disposed of.

Wastes Disposal Location: The liquids were taken to SWD and the solids will be taken to Clean

Harbors.

Agencies Involved: TAT and MHA

Updates

Date: 3/8/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on the facility site according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.